BUILDING SAFETY CERTIFICATE

NO. 28 69

Dated :-98/04/2025

It is certified that the existing building K. John Public School, at Pipla, Besa road, Tah. Nagpur, District Nagpur. (Name of the building or premises) at Besa Pipla road, Nagpur (address) is having block (s)/Floor(s) as per details below:

Details of Block (s) in	Block	Block	Block	Block	Block	Block
School 3	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor (s) in the	G+2	200				
block			a / ** /			-

The Building is owned/occupied by K. John Public School, at Pipla, Besa road, Tah. Nagpur, District Nagpur. (Name of the Institution) have complied with the Building Safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public Work Division No. 2 (Name of Department / Govt.) on 16/05/2025 (Date of Inspection) in the presence of Dr. K. V John, President The Montfort Educational Society and that the building / premises is fit for occupancy for running school with effect from 2025 - 26 for a period of 1 (One) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Structural stability should be examined also with reference to location, altitude, intensity of wind floor.

2. Fire safety inspection / report should be done by agency separately

Issued on 98/04/2019 at Nagpur by.

Stick out whichever is not applicable. In case of block is more than six use separate

sheet for detail.

The Montfort Educational Society

Nagpur

Sub Divisional Engineer **Public Works Sub Division**

(Rural) Nagpur.

Signature with Seal

Name:

Designation:

Executive Marzine er

Name & Address of Department/ Office:

Public Works Division No. 2, Nagpur.

(Assistant Engineer & above officer of concerned Gov. Department only)